Folding Pocket Thermometer

- ±0.3°C accuracy
- CAL CHECK®
- Stainless steel folding probe with penetration tip
- Enables angled measurement
- Ergonomic
- Auto shut-off

The folding Checktemp[®]4 provides practical temperature measurement for the food service industry.

Special attention was given to the ergonomic form of Checktemp®4. This thermometer fits comfortably and securely in your hand. The LCD on the side of the handle is easy to see and read. The fast responding, fold-away probe is made of high quality, stainless steel and can penetrate semi-frozen and semi-solid foods like meats, ice cream and cheeses. When you are finished using your Checktemp®4, wipe the probe clean and fold it away. Checktemp®4 automatically turns OFF so you can safely carry it in your pocket.

CAL CHECK®

As you unfold the stainless steel probe, the Checktemp® 4 automatically turns ON and immediately performs a calibration test. This unique HANNA feature, CAL CHECK®, provides the security of knowing you have accurate measurements. CAL CHECK® also lets you know if your battery level is low or if your meter requires recalibration.



SPECIFICATIONS	HI 151-00 (Checktemp®4C)	HI 151-01 (Checktemp®4F)
Range	-50.0 to 220°C	-58.0 to 428°F
Resolution	0.1°C (-50.0 to 199.9°C); 1°C (200 to 220°C)	0.1°F (-58.0 to 199.9°F); 1°F (200 to 428°F)
Accuracy	±0.3°C ±1 digit (-20.0 to 90.0°C); ±1% F.S. ±1 digit (outside)	±0.5°F ±1 digit (-4.0 to 194.0°F); ±1% F.S. ±1 digit (outside)
Calibration Check	automatic, at start-up	
Probe	stainless steel probe with penetration tip; 117 x dia 3.5 mm (4.6 x dia 0.14")	
Battery Type / Life	1.5V AA / approximately 25,000 hours of continuos use; auto-off after 8 minutes of non-use	
Environment	0 to 50°C (32 to 122°F); RH max 95%	
Dimensions	165 x 50 x 20 mm (6.5 x 2.0 x 0.8")	
Weight	100 g (3.5 oz.)	

ORDERING INFORMATION

HI 151-00 (Checktemp®4 C) is supplied complete with battery and instructions HI 151-01 (Checktemp®4 F) is supplied complete

with battery and instructions HI 151-001 (Checktemp®4 C) is supplied complete with calibration certificate, battery and instructions HI 151-011 (Checktemp®4 F) is supplied complete with calibration certificate, battery and instructions HI 151-02 (Checktemp®4 C) ±0.5°C accuracy, without CAL CHECK is supplied complete with battery and instructions



2